


1614

FS02.1B



FIRST FLOOR PLAN - EXISTING 1:100

no. revision




reproduced or otherwise dealt with without written permission of Architecture Matters Pty Ltd.

508 Queensberry Street North Melbourne, VIC, 3051 T (03) 9329 7063 F (03) 9329 7919

www.architecturematters.com.au


99A CARLISLE STREET, ST KILDA, 3182






DRAWING FIRST FLOOR PLAN -EXISTING Scale: AS SHOWN @ A3 Date: 16/06/2016





FS02.2



www.architecturematters.com.au

PO Box 285 nth melbourne vic 3051

1614

Date: 16/06/2016

DRAWING

FS02.3B

FIRST FLOOR PLAN -DESIRED Scale: AS SHOWN @ A3

DESIRED



Children Services Program WORKING GROUP – TECHNICAL MEETING ELWOOD CHILD CARE CENTRE



6

MINUTES: 10 MAY 2016 010:00AM –11:30AM, Emerald Room, St Kilda Town Hall Offices

PARTICIPANTS:

Attendees	Role	Attendance or delegate			
Joe Gangi	Chair – Building Options Study Coordinator	Present			
Anthony Gionfriddo	Architect, Architecture Matters P/L	Present			
Mark Thompson	Manager Asset Planning & Property	Present			
Janelle Bryce	Manager, Family, Youth, Children	Present			
Vanessa	Elwood Child Care Centre	Present			
Ness	Elwood Child Care Centre	Present			
Kass	Elwood Child Care Centre	Present			
Accompanying Documentation					
None					

AGENDA ITEMS:

ltem #	Description	Action	Date
1	Introductions		
2	Centre Capacity and General Discussion The centre is currently licenced for 39 children and is running	Note	
	almost at 35 The current (and typical) ratio is as follows:		
	 13 - Kinder children (>4 yrs) 10 - (3 - 4 yrs) 4 - Toddlers (2 - 3 yrs) 8 - Babies (0 - 2 yrs) 		
	Note: Elwood does not have any desire to increase the numbers / capacity as it currently services a niche market.		
	Currently the back garden is used by the Kinder kids and 3- 4 yrss while the front garden is used by the Toddlers and Babies.		
3	Techer Numbers - the current numbers are as follows: • Kinder children (>4 yrs) = 2 • $(3 - 4 yrs) = 1$ • Toddlers $(2 - 3 yrs) = 2$ • Babies $(0 - 2 yrs) = 2$ • Admin staff $- 2 - 3$ (varies) • Educators $- 2 - 3$ (varies) • Cook - 1	Note	
	Total staff number = 12 - 14		



Children Services Program WORKING GROUP – TECHNICAL MEETING ELWOOD CHILD CARE CENTRE



MINUTES: 10 MAY 2016 010:00AM –11:30AM, Emerald Room, St Kilda Town Hall Offices

tem #	Description	Action	Date
4	Child / Area Ratios	Note	
	The Education and Care Services National Regulations requires 3.5sqm of unencumbered space inside and 7sqm outside.		
	The current internal floor area will need to be confirmed but external appears to exceed the requirement.		
5	DDA Issues	Note	
	The following items were raised by The Avenue:		
	 Stairway is narrow and steep and is difficult for an existing staff member with disabilities (on maternity leave) to use No DDA facilities or office space on ground level 		
	JG to check the handrail permit/dispensation issued with Building Solutions	JG	ASAP
6	Elwood Requirements – Desired	Note	
	The following items were raised for inclusion in scope as 'desired' items:		
	 Flexible floor space enabling alteration to spaces to accommodate changes in children numbers. Office space downstairs for meeting/planning/DDA. Ideally this would be centrally located for visibility for entrance – similar to St Kilda / Balaclava Kinder. Possible consideration for a reception desk Possibility of converting the Kinder space into an internal area with openable doors to access the backyard. Visibility of the toilets in the kinder area to be improved from the backyard. Reconfigure staircase and look at the possibility of a personnel lift. Possibility of relocating the kitchen to the opposite side so that all amenities are on the same side leaving space for additional child area improving access to front and back yards and also to possible admin area and reception. Improve flow from all areas to amenities and playgrounds as well as entrance space. Current control point is within the play area at front and poses a security risk – concept to eliminate this. 		
7	Next Meeting JG advised that Elwood will be consulted further upon development of the concept options. This will be an opportunity to	Note	



deworl

3.00 TENNYSON STRET- ELWOOD CHILDCARE CENTRE

3.01 **Electrical Services**

3.01.01 Power

The general switchboard, power and lighting reticulation is in average condition. The switchboard is required to be upgraded to comply with current AS3000 regulations for RCD protection.

For the installation of the proposed lift, the existing MSB would need to be replaced with a potential electrical supply upgrade.

Existing wiring to be modified to suit proposed modifications.

3.01.02 Lighting

Typically, the lighting throughout the facility is average to poor condition.

The scope of works proposed to replace lighting to modified/new areas including;

- Kitchen
- Hall/Foyer
- Office/Meeting
- WC areas
- Playroom 2 Extension area
- New Baby Change & WC's

3.01.03 Emergency Lighting

Currently there is no emergency lighting test switch. With the proposed MSB upgrade, an emergency lighting test switch is proposed to be provided. Existing fittings where currently compliant shall be retained, new emergency lighting to be provided where required.

3.01.04 Communication Systems

Communications systems are proposed to be retained and modified where required to suit new proposed layout.

3.02 Hydraulic Services

3.02.01 Cold Water Supply

> The cold water supply and reticulation is proposed to be retained, modified and extended to suit new laundry, new WC locations and extension, baby change.

Jevek icative 3.02.02 Sewer Service

it's

The existing sewer is proposed to be modified and extended to suit the proposed WC's, baby change area and new laundry space.

3.02.03 Domestic Hot Water System

The existing gas fired hot water system is proposed to be maintained with pipework modified to serve all required fixtures including new fixtures.



de work

3.02.04 Rainwater Service

The existing rainwater system is proposed to be retained.

3.03 **Mechanical Services**

3.03.01 Cooling & Heating Systems

The facility is served by numerous split systems of varying age and condition. Where possible the existing A/C units and condenser units are proposed to be retained to serve the existing areas.

The new office/meeting room is proposed to be provided with a new split system.

<text> The building is proposed to be retained as a naturally ventilated building throughout. The existing rangehood is proposed to be relocate to suit the new

The new WC areas at ground and first floor, laundry and baby change areas are



3 46 Tennyson st, Elwood

3.1 General

The building at 46 Tennyson st, Elwood is a double storey building, with solid brick walls, a mixture of single brick and lightweight internal ground floor walls, lightweight first floor walls and tiled roof. This building also has a previous single storey extension to the back of the building, with lightweight roof & walls, and slab on ground.

3.2 **Previous investigations**

Previous report and investigations have been undertaken by Wood & Grieve Engineers in October 2013. The report provided noted that the building is in generally good condition. The main concern was rising damp in some areas of the building, as well as inadequate connections of the pergola (which has been enclosed to form an internal room) to the existing building.

3.3 Geotechnical reports

A geotechnical investigation was untaken as part of the additional investigations at the site by Civil Test Pty Ltd on 28th May 2016, and a copy of their report is attached in Appendix A.

The site has been classified as Class M in accordance with AS2780. The existing strip footing exposed varied from 350-500 deep and is founded in silty clay/silty sand. To satisfy the current standard, for articulated full masonry in Class M sites, the footing should be 600 deep. Therefore the existing footings are not in accordance with the current standard.

3.4 Observations The building

The building at 46 Tennyson st, Elwood is in generally good condition. While the footings are not in accordance with current standards, the masonry is in good condition with only minor cracking.


Additional investigation was undertaken, and the timber floor throughout the hall area needs to be re-stumped and sub-floor ventilation added, as shown on the structural sketches



Nor

provided. The issues with rising damp are likely due to a lack of subfloor ventilation in addition to low clearance between the existing floor joists and the natural ground. The floor in the hall section of the building is to be re-stumped, and subfloor vents are to be provided along the northern side of the building.


Another area of concern is a section of the roof from a previous extension, which appears to have been originally only a pergola type structure, to which cladding was later added. This area of the extension is to be removed and replaced with new slab, short retaining wall, lightweight walls and roof in accordance with the sketches provided. Other aesthetic and functional changes proposed by the architect are also documented on sketches S007 through S013.




	Up
EXISTING JI 14MI TO BE CONFIRMED ON SITE BY BUILDER.	SEWER IN EAGEMENT APPPOX 3.3m IDEEP. TO BE CONFIRMED ON SITE BY BUILDER
	NEW TIMBER FLOOR 90 X45 FI7 KOHW JOISTS AT450 CTS, 1500 MAX SPAN
to AT Joinits) n Hotherer is people	90×90 FFF KOHW BEARERS 1600 MAX SPAN ON 100×100 CONCRETE STUMB WITH 400×400 ×200 DEEP PAD.
PROJECT CITY OF PORT PHILLIP CONDITION AUDITS 46 TENNYSON STREET, ELWOOD 3184	DRAWING GROUND FLOOR PLAN - DESIRED Scale: AS SHOWN @ A3 Date: 30/05/2016
PROJECT NUMBER	FS02.1B

Rev 1 - 3/6/16 - PRELIMINARY ISSUE

Rev 2 - 10/6/16 - PRELIMINARY PRICING ISSUE







CITY OF PORT PHILLIP CONDITION AUDITS

DRAWING FIRST FLOOR PLAN -DESIRED Scale: AS SHOWN @ A3 Date: 30/05/2016

FS02.3B





Quantity Surveyors

DDH Quantity Surveyors Pty Ltd ACN 651 583 854 ABN 41 651 583 854

integrity

A: 2.01/ 17-19 Yarra Street, Abbotsford VIC 3067 T: 03 9417 5505 W: www.ddh.comau

Tom Temay Property Development Associate | Property and Assets 99a Carlisle Street, St Kilda VIC 3182

24 January 2022

City of Port Phillip

46 Tennyson Street, Elwood VIC 3184

Dear Tom,

In accordance with your instructions, we have prepared a Revised Preliminary Cost Plan based on drawings provided, and report herein the estimated total project cost as follows:

Building & Siteworks (Desired Scope)

Estimated Total Project Cost Based on Project Being Tendered in January 2024

Exclusions

In compiling this costing, we have not allowed for the following:

Bank charges and financing costs

Future maintenance & replacement of equipment due to wear & tear

Energy consumption costs

Decanting costs

Major upgrade to existing

Rainwater tanks

Solar panels

Retaining walls

Contaminated soil removal

Cost escalation beyond January 2024

We trust that this is satisfactory for your purposes at this stage.

ours faithfully,

Gareth Tiong Director

Member of AIQS - MAIQS 10619 Registered Building Practitioner - QS 47529 Excluding GST \$1,720,000.00

City of Port Phillip 46 Tennyson Street, Elwood VIC 3184 Revised Preliminary Cost Pan

Summary

Desired Scope 24 January 2022							
	the same	Area m2	Rate	Estimated			
	Items	FECA	\$/m2	Cost	. 🤆		
1.0	Demolition			\$42,205.00	\sim		
2.0	Alteration & Addition to Existing Building	337.0	\$3,265.13	\$1,100,350.00			
3.0	Siteworks Inc. Landscaping			\$47,445.00			
Sub T	otal Excluding GST		•	\$1,190,000.00			
4.0	Cost Escalation to Tender (January 2024)		У× С	\$110,000.00			
Estim	ated Total Contract Sum Excluding GST		. 20	\$1,300,000.00			
5.0	Contingency During Construction		S	\$130,000.00			
Estim	ated Net Project Cost Excluding GST	G	o o.	\$1,430,000.00			
6.0	Consultant Fees Inc. PM	X.	R	\$200,000.00			
Estim	ated Gross Project Cost Excluding GST	x yr	S	\$1,630,000.00			
7.0	Authority Charges, Planning Permit, Building Permit & Etc.			\$40,000.00			
8.0	Loose Furniture & Equipment	6		\$50,000.00			
Estim	ated Total Project Cost Excluding GST	21		\$1,720,000.00			
	Add - GST			\$172,000.00			
Estim	ated Total Project Cost Including GST			\$1,892,000.00			

Covid 19 Impact

This Cost Plan is prepared based on normal conditions and current material cost. The tender prices may be affected by unforeseeable consequences of Covid-19 pandemic such as spike in material costs, shortage of timber supply, unanticipated material delivery delay, government mandated shutdowns, on-site outbreak/ quarantine or the like.

Drawings Used Architecture Drawing (Desired Scope) FS02.0, FS02.1B, FS02.2, FS02.3B Structural Drawings Marked up structural drawings Access Report Access Consulting Access report dated 9 June 2016

City of Port Phillip 46 Tennyson Street, Elwood VIC 3184

Contact Details

Client

City of Port Phillip

		24 January 2022	N
Discipline	Consultant	Phone Number	20,
Architect	Architecture Matters	03 9329 7063	
Landscape Architect	ТВА	tille	
Structure Engineer	Adams Consulting Engineers	03 8600 9700	
Civil Engineer	ТВА	\$	
Mech. & Elec. Engineer	тва	28	
Hydraulic Engineer	тва		
Quantity Surveyors	DDH	03 9417 5505	

bh bh

Elemental Summary

Details: Preliminary Cost Plan - Rev.1

Project: City of Port Phillip - 46 Tennyson Street,

46 Tennyson Street, Elwood VIC 3184

Building: Elwood

Code	Description	Quantity	Unit	Rate	Total
	Description Demolition Demolition Sub Total Excluding GST Building - Addition & Alteration Preliminaries Substructure Columns Staircase Roof Framing, Roofing & Roof Plumbing External Walls Internal Walls Internal Walls Vindows, Internal Glazed Screens & Window Furnishings Doors & Hardware Wall Finishes Floor Finishes Ceiling Finishes Joinery & Toilet Partitions Toilet Accessories, Kitchen Appliances & Signs Painting Sanitary Fixtures & Plumbing Electrical Services Mechanical Services Lift Fire Protection Design Variable Sub Total Excluding GST Siteworks Inc. Landscaping				
01	Demolition				42,20 5
	Sub Total Excluding GST			~	42,20
	Building - Addition & Alteration			22	
02	Preliminaries			11	132,52
03	Substructure		c.o	>	39,420
04	Columns		illi		3,000
05	Staircase	20			23,120
06	Roof Framing, Roofing & Roof Plumbing	.10			20,690
07	External Walls	300			59,650
08	Internal Walls	NS De	,		75,70
09	Windows, Internal Glazed Screens & Window Furnishings				67,000
10	Doors & Hardware	× 65			32,30
11	Wall Finishes	101			25,00
12	Floor Finishes				58,69
13	Ceiling Finishes				17,700
14	Joinery & Toilet Partitions				58,550
15	Toilet Accessories, Kitchen Appliances & Signs				31,000
16	Painting All Painting				26,96
17	Sanitary Fixtures & Plumbing				94,000
18	Electrical Services				125,390
19	Mechanical Services				47,30
20	Lift S NO.				75,000
21	Fire Protection				3,00
22	Design Variable				84,359
	Sub Total Excluding GST	337	m2	3,265.13	1,100,350
	Siteworks				
23	Siteworks Inc. Landscaping				47,44
-					1,190,000

	Project: City of Port Phillip - 46 Tennyson Street, Deta Building: Elwood	ils: Prelimin	ary Cost	Plan - Rev.1	
	46 Tennyson Street, Elwood VIC 3184				
Code	Description	Quantity	Unit	Rate	Total
01	Demolition				
	Preliminaries			C	
	Preliminaries	1	item	5,505.00	5,505
				22	
	Demolition Works			11	
	Demolition works where required (FECA)	337	m2	100.00	33,700
			Ĭi,		
	Asbestos Removal	>	e		
	Allow for asbestos removal	<u>`1</u>	ps	3,000.00	3,000
_	Asbestos Removal Allow for asbestos removal Demolition Preliminaries Preliminaries Fully Enclosed Covered Area (FECA) FECA to ground floor alteration & addition area FECA to first floor alteration area Total FECA - Ground & First Floor Preliminaries Substructure Screw Piles 25Kn screw pile (SP1)	3	0		42,205
02	Preliminaries	NS of			
	Preliminaries		•		
	Preliminaries		item	132,521.00	132,521
	in ^{es} v				
	Fully Enclosed Covered Area (FECA)				
	FECA to ground floor alteration & addition area	257	m2		
	FECA to first floor alteration area	80	m2		
	Total FECA - Ground & First Floor	337	m2		
	Preliminaries				132,521
03	Substructure				
	Screw Piles				
	25Kn screw pile (SP1)	8	no.	1,250.00	10,000
	25Kn screw pile (SP1)				
	Blinding & reinforced concrete pad footing (PF2)	3	m3	1,000.00	3,000
	in 19 yet				
	Timber Floor Structure				
	Timber floor structure comprising 90 x 45 F17 KDHW joists at 450 cts., 90 x 90 F17 KDHW bearers & 100 x 100 concrete stump with 400 x 400 x 200 deep pad	7	m2	250.00	1,750
	Lift FFL with timber batten & FC sheet over existing slab to staff wc & baby change	19	m2	150.00	2,850
2	Wc	_5	-		_,
	2/ 300 x 42 LVL15 floor beam (FB1)	2	m	160.00	320
	2/ 200 x 42 LVL 15 ditto (FB2)	2	m	120.00	240
	Investigate & repair damp issues to existing building subfloor & rectify (2b, 13)	1	item	2,500.00	2,500
	Concrete Floor Structure				
	100 Thk. reinforced concrete raft slab with SL82 top complete with edge beam, internal beam, 0.2 thk. vapour barrier, 50 thk. sand bed, edge form & excavation	26	m2	350.00	9,100
	125 Thk. reinforced concrete slab with SL82 top & bottom complete with ditto	16	m2	400.00	6,400

	Project:City of Port Phillip - 46 Tennyson Street,DBuilding:Elwood	Details: Prelimir	tails: Preliminary Cost Plan - Rev.1			
	46 Tennyson Street, Elwood VIC 3184					
Code	Description	Quantity	Unit	Rate	Total	
03	Substructure				(Continued)	
	Allow for drill, dowel bars & epoxy to existing edge beam	1	item	2,000.00	2,000	
				~		
	Termite Treatment			22		
	Allow for termite treatment	42	m2	30.00	1,260	
	Substructure		ċ	leo	39,420	
04	Columns		<u></u>			
	Column & Double Studs		61			
	2/ 90 x 45 MGP10 double stud (DS)	9	no.	250.00	2,250	
	2/ 90 x 45 F17 KDHW double stud (DS1)		no.	250.00	250	
	Sundry		item	500.00	500	
	Columns				3,000	
05	Staircase	<u>~ 65</u>				
	Staircase					
	1000 Wide flight with intermediate landing & balustrade/ handrail	1	item	20,000.00	20,000	
	Stair nosing	1	item	1,620.00	1,620	
	Enclosed stair soffit or barrier	1	item	1,500.00	1,500	
	Sundry Columns Staircase Staircase 1000 Wide flight with intermediate landing & balustrade/ handrail Stair nosing Enclosed stair soffit or barrier Staircase Roof Framing, Roofing & Roof Plumbing Retain existing roof framing Steel roof beam (RB7, RB8) 240 x 42 LVL 15 roof beam (RB9)				23,120	
06	Roof Framing, Roofing & Roof Plumbing					
	Roof Framing					
	Retain existing roof framing		note			
	Steel roof beam (RB7, RB8)	0.36	t	10,000.00	3,600	
	240 x 42 LVL 15 roof beam (RB9)	2	m	70.00	140	
	2/ 240 x 42 LVL 15 roof beam (RB9A)	5	m	140.00	700	
	130 x 45 LVL 15 rafter at 600 cts (R2)	15	m2	50.00	750	
	240 x 42 LVL 15 rafter at 600 cts. (R3)	41	m2	70.00	2,870	
	Roof bracing (BR1)	19	m	30.00	570	
	Reofing					
	Retain existing roofing		note			
-7,	New roofing to building addition area	42	m2	180.00	7,560	
	to.					
X	Roof Plumbing					
	Retain existing roof plumbing		note			
	New roof plumbing to building addition area	1	item	4,500.00	4,500	
	Roof Framing, Roofing & Roof Plumbing				20,690	
07	External Walls					
	Repair Works					

	Project: Building:	City of Port Phillip - 46 Tennyson Street, De Elwood	atails: Prelimin	ary Cost	Plan - Rev.1	
		46 Tennyson Street, Elwood VIC 3184				
Code		Description	Quantity	Unit	Rate	Total
07	External Wa	alls				(Continued)
	Repair & re	place missing/ damaged shingles to front facade of building (1)	1	item	3,000.00	3,000
	Sub floor ve	ent to existing wall	2	no.	200.00	400
	External W	alls			711	
	140 Thk. blo	ockwork retaining wall with reo & grout fill (RW1)	13	m	300.00	3,900
	120 Thk. ex	ternal wall	8	m	1,400.00	11,200
	150 Thk. dit	to	12	m	1,500.00	18,000
	250 Thk. dit	to	14	m	1,600.00	22,400
	<u>Timber Lint</u>	tto	NS 25	Se.		
	90 x 45 MG	P10 lintel (TL1)		m	100.00	100
	130 x 42 LV	L 15 ditto (TL2)	2	m	50.00	100
	150 x 42 LV	L 15 ditto (TL3)	8	m	50.00	400
	Wall Bracin	es buille and				
	Wall strap b	prace (WB)	1	no.	150.00	150
L	External Wa	alls				59,650
08	Internal Wa	lls AIC AIL				
	Repair Wor	<u>ks</u>				
	Replace wa	llpaper to first floor storeroom (3)	1	item	5,000.00	5,000
	Repair mino	of damage & noies (4)	1	item	inc. above	0
	Repair wate	er damage to walls where required (9)	1	item	inc. above	0
	Repair crac	ked walls (10)	1	item	inc. above	0
	Internal Wa	er damage to walls where required (9) ked walls (10)				
	110 Thk. int	ernal wall partition	5	m	560.00	2,800
	140 Thk. dit	tto	35	m	600.00	21,000
	240 Thk. dit	to	23	m	650.00	14,950
JI	Lift Shaft W	Valls				
Υ	¹ O ¹	inforced block lift wall	9	m	2,500.00	22,500
	Wall lining t			m	700.00	6,300
	5					
	Steel Lintel	<u>s</u>				
	Steel lintel ((L2)	0.27	t	10,000.00	2,700

	Project: City of Port Phillip - 46 Tennyson Street, D Building: Elwood	Details: Prelimin	ary Cost	Plan - Rev.1	
	46 Tennyson Street, Elwood VIC 3184				
Code	Description	Quantity	Unit	Rate	Total
08	Internal Walls				(Continued)
	<u>Timber Lintels</u>				$\overline{\mathbf{O}}$
	90 x 45 MGP10 lintel (TL1)	1	m	100.00	100
	Wall Plate			<i>n</i> ,	
	130 x 42 LVL 15 wall plate (WP2)	7	m	50.00	350
	Internal Walls		ji)		75,700
09	Windows, Internal Glazed Screens & Window Furnishings		en		
	Repair Works	· · ·)		
	Replace exterior window panels where gaps/ rotting have occurred (6)	°∑1	item	4,000.00	4,000
	Repair jamming window frames where required (11)	JOTKS COT	item	4,500.00	4,500
	Windows	14 . Os			
	New window	14	m	3,000.00	42,000
	<u>Flyscreens</u>				
	Replace flyscreen to external front windows (8)	1	item	1,500.00	1,500
	Windows, Internal Glazed Screens & Window Furnishings Repair Works Replace exterior window panels where gaps/ rotting have occurred (6) Repair jamming window frames where required (11) Windows New window Flyscreens Replace flyscreen to external front windows (8) Internal Glazed Screens New internal glazed screen Window Furnishings Allow for window furnishings	9	m	1,000.00	9,000
	Window Furnishings	1	item	6,000.00	6,000
	Windows, Internal Glazed Screens & Window Furnishings				67,000
10	Doors & Hardware				
	External Doors				
	Single swing door, frame & hardware	1	no.	1,200.00	1,200
	Unequal double swing glazed door, frame & hardware	2	no.	3,600.00	7,200
~	Internal Doors				
· // `	Single swing door, frame & hardware	12	no.	1,200.00	14,400
Ś	Single sliding door, frame & hardware	1	no.	1,500.00	1,500
	Door Control System				
	Door control system	1	item	8,000.00	8,000
	Doors & Hardware				32,300
11	Wall Finishes				
	Wall Covering				

	Project: City of Port Phillip - 46 Tennyson Street, De Building: Elwood 46 Tennyson Street, Elwood VIC 3184	e tails: Prelimin	ary Cos	t Plan - Rev.1	
Code	Description	Quantity	Unit	Rate	Total
11	Wall Finishes				(Continued)
	Allow for wall vinyl / wall tiles/ splashback & waterproofing	1	item	25,000.00	25,000
	Wall Finishes			~ ^ N	25,000
12	Floor Finishes			20	
	Repair Works			<i>n</i> ,	
	Repair & make good existing floor surface (18, 20)	301	m2	20.00	6,020
	Floor Covering	>	en		
	Floor covering to ground floor	236	m2	130.00	30,680
	Ditto to first floor	~ 65	m2	130.00	8,450
	Waterproofing to wet area	× 43	m2	35.00	1,505
	Tactile indicators to stair		item	1,500.00	1,500
		. 005			
	Skirtings	10.			
	Skirtings (FECA)	301	m2	35.00	10,535
	Floor Finishes				58,690
13	Ceiling Finishes				
	Repair Works			2 000 00	2 000
	Repair water damage to ceilings where required (9)	1	item	3,000.00	3,000
	Ceilings Lining	259	mz	35.00	9,065
	Floor covering to ground floor Ditto to first floor Waterproofing to wet area Tactile indicators to stair Skirtings Skirtings (FECA) Floor Finishes Ceiling Finishes Repair Works Repair water damage to ceilings where required (a) Make good to existing ceiling where required (a) Make good to existing ceiling where required (b) Make good to existing ceiling where required (b) Allow for new ceiling insulation	49	m2	100.00	4,900
	Allow for new ceiling insulation		m2	15.00	735
L	Ceiling Finishes				17,700
14	Joinery & Toilet Partitions				
	Cupboards, Drawers & Fittings				
	Sundry joinery to ground & first floor (FECA)	337.00	m2	150.00	50,550
- 5	AND				
	Toilet Partitions				
	Allow for toilet partitions & doors	1.00	item	8,000.00	8,000
	Joinery & Toilet Partitions				58,550
15	Toilet Accessories, Kitchen Appliances & Signs				
	Toilet Accessories				
	Toilet accessories	1	item	18,000.00	18,000
·					

	Project: City of Port Phillip - 46 Tennyson Street, Building: Elwood	Details:	Preliminary Cost Plan - Rev.1			
	46 Tennyson Street, Elwood VIC 3184					
Code	Description	(Quantity	Unit	Rate	Total
15	Toilet Accessories, Kitchen Appliances & Signs					(Continued)
	Kitchen Appliances				G	.
	Kitchen appliances - cooktop, dishwashers & oven		1	item	10,000.00	10,000
	Fridges & microwave by others			note		
	Internal Signs				601	
	Internal signs		1	item	3,000.00	3,000
	Toilet Accessories, Kitchen Appliances & Signs			0		31,000
16	Painting		j,	2		
	Internal & External Painting		S	<u>.</u>		
	Internal external painting where required (FECA) (1a, 3c, 2	, 9, 10)	337	m2	80.00	26,960
	Painting	101	c'a			26,960
17	Sanitary Fixtures & Plumbing	ye building and land	5			
	Upgrade Works	in Sint				
	Ground Floor	illon d'r				
	Retain existing kitchen sink & tap	Pri Sti		note		
	Baby change & w/c	10,0	1	item	8,000.00	8,000
	Staff W/C		1	item	8,000.00	8,000
	Child W/C	UII.	1	item	8,000.00	8,000
	Child W/C 2	V	1	item	25,000.00	25,000
	Laundry/ store		1	item	5,000.00	5,000
	First Floor					
	UA W/C		1	item	10,000.00	10,000
	Staff room kitchenette		1	item	11,000.00	11,000
	Connection					
	stillsade		1	item	2,000.00	2,000
	Drinking Fountains		1	item	5,000.00	5,000
			T	item	5,000.00	5,000
-1),	Boiling Water Units					
	Boiling water units		1	item	12,000.00	12,000
V	Sanitary Fixtures & Plumbing					94,000
18	Electrical Services					
	Upgrade Works					
	Upgrade switchboard & reconfigure lighting, power, data	& etc. (FECA)	337	m2	270.00	90,990
	Hearing augmentation		1	item	20,000.00	20,000

	Project: City of Port Phillip - 46 Tennyson Street, I Building: Elwood	Details: Preliminary	Preliminary Cost Plan - Rev.1		
	46 Tennyson Street, Elwood VIC 3184				
Code	Description	Quantity	Unit Rate	Total	
18	Electrical Services			(Continue	
	Testing, Commissioning & Etc.			G ·	
	Testing, commissioning & etc.	1 ite	m 3,000.00	3,00	
	Builder's Works & Coordination		111		
	Builder's works & coordination	1 ite	m 11,400.00	11,40	
	Electrical Services		ill'i	125,39	
19	Mechanical Services	20			
	Upgrade Works	.10			
	Mechanical services	1 ite	m 30,000.00	30,00	
	Exhaust system to W/Cs	OT COT THE	m 10,500.00	10,50	
	Mechanical Services Upgrade Works Mechanical services Exhaust system to W/Cs Testing, Commissioning & Etc. Testing, commissioning & etc. Builder's Works & Coordination Builder's works & coordination Builder's works & coordination Mechanical Services Lift Passenger Lift Passenger lift to serve 2 floors Builder's works & coordination	1 and 1 ite	m 2,500.00	2,50	
	Builder's Works & Coordination		4 200 00		
	Builder's works & coordination	1 ite	m 4,300.00	4,30	
20	Mechanical Services			47,30	
	Passenger Lift				
	Passenger lift to serve 2 floors	1 ite	m 70,000.00	70,00	
	Builder's works & coordination	1 ite	m 5,000.00	5,00	
	Lift SS NO			75,00	
21	Fire Protection				
	Fire Protection	1 ita	m 2 000 00	2.00	
	Fire Protection	1 ite	m 3,000.00	3,00 3,00	
22	Design Variable			3,00	
	Design Variable				
	Allow for variance in design during documentation development	1 ite	m 84,359.00	84,35	
<u>., 1</u>	Design Variable	1 110		84,35	
23	Siteworks inc. Landscaping			54,50	
	Preliminaries				
*	Preliminaries	1 ite	m 5,626.00	5,62	
	<u>Clear Site</u>				
	Clear site as required	49 m	2 10.00	49	

Bi Di	Description Siteworks inc. Landscaping Bulk Cut & Fill Bulk cut & fill to building addition area (GFA) Ditte to rome & landing				(Continued
<u>Bi</u> Bi Di	Bulk Cut & Fill Bulk cut & fill to building addition area (GFA)				
Di				(*
	Ditto to comp & landing	42	m2	50.00	2,100
<u>E)</u>	Ditto to ramp & landing	7	m2	20.00	140
	External Signage			<i>dII</i> .	
U	Jpgrade signage to front of building (4d)	1	item	10,000.00	10,00
Fy	External Ramp & Landing		yer!		
Co	Concrete ramp with SL82 top, 0.2 thk. polythene membrane, 50 thk. sand bed & 50 hk. crushed rock	ر من ر م	m2	250.00	1,75
	Balustrade/ handrail	K 23	m	600.00	7,80
Ta	Factile indicators		item	1,575.00	1,57
D	Drill, dowel bars & epoxy to existing paving	and 1	item	500.00	50
<u>Si</u>	External Ramp & Landing Concrete ramp with SL82 top, 0.2 thk. polythene membrane, 50 thk. sand bed & 50 hk. crushed rock Balustrade/ handrail Factile indicators Drill, dowel bars & epoxy to existing paving Side Fence & Gate Side fence & gate Repair Works Repair over verandah to rear of kinder playroom 2 (2) Repair over verandah to rear of kinder playroom 2 (5)	•			
Si	Side fence & gate	2	m	500.00	1,00
R	Repair Works				
Re	Repair over verandah to rear of kinder playroom 2 (2)	11	m2	150.00	1,65
Re	Replace external fencing panels to boundary fences (5)	1	item	6,000.00	6,00
Re	Reposition/ replace front entrance gate button (7)	1	item	500.00	50
Le	evel area with full turf coverage to rear verandah to fix uneven surfaces (12) Design Variable	1	item	4,000.00	4,00
	Design Variable				
	Allow for variance in design during documentation development	1	item	4,314.00	4,314
Si	Siteworks inc. Landscaping				47,44